



APPROX. 5240 L.F. OF EXISTING FARM FENCE (FIGURE 13)

CHAIN LINK GATE (FIGURE 12)

APPROX. 1700 L.F. OF PROPOSED 4 STRAND WIRE FENCE (FIGURE 11)

FULL-TIME CARE TAKER/SECURITY CHECKPOINT
BLACK VINYL COATED CHAIN LINK GATE WITH MECHANICAL OPERATOR (FIGURE 10)

APPROX. 1700 L.F. OF BLACK VINYL COATED CHAIN LINK FENCE (FIGURE 9)


APPROX. 1600 L.F. OF PROPOSED CHAIN LINK FENCE TO MATCH EXISTING CHRIS AND HANSON LAKE SYSTEM (FIGURE 8)

EXISTING CHAIN LINK GATE (FIGURE 1)

EXISTING CHAIN LINK FENCE (FIGURES 5 & 4)

EXISTING CHAIN LINK GATE (FIGURE NO. 1 & 2)

- LEGEND**
- X — CHAIN LINK FENCE
 - X — DECORATIVE FENCE
 - X — 4-STRAND SLICK WIRE FENCE



AS SHOWN	DATE:	DESIGNED BY:	CHECKED BY:	REVISION:
1-25-10	JLT	JLT	JLT	###

LEISURE VILLAGE
CENTURY DEVELOPMENT
FENCING AND SECURITY EXHIBIT

TDS
 THOMPSON, DREESSEN & DORNER, INC.
 Consulting Engineers & Land Surveyors
 10836 OLD MILL ROAD OMAHA, NEBRASKA 68154
 PHONE: 402.330.8860 FAX: 402.330.5866 EMAIL: TDSDMAIL@TDSOCO.COM
 WEBSITE: WWW.TDSOCO.COM

169-193
SHEET 1 OF 1